


REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-6462

CLIENT **Douglas Aircraft Company**
Internal Mail Code 74-41
3855 Lakewood Boulevard
Long Beach, California 90846
SAMPLE Attention: Ron Fornator
Storm Drain Inspection - March
P.O. No.: T & M-23465-C

DATE April 10, 1991
RECEIVED March 26, 1991
LABORATORY NO. 46729

INVESTIGATION

Analysis as requested by the CRWQCB
for NPDES Permit Number CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on March 22, 1991, at the Douglas Torrance Facility. The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory and analyzed according to the American Public Health Association's "Standard Methods," 17th Edition. The results are as follows:


<u>Sample I.D.</u>	<u>Date</u>	<u>Time</u>	<u>Flow-gpd</u>	<u>Temp, °F</u>	<u>pH, units</u>
Torrance	3/22/91	09:40	no flow*	75	8.2

*No storm drain water discharging from skimmer. Grab sample taken from discharge point.

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.

Brian C. Puncochar

Brian C. Puncochar, Manager
Water and Waste Laboratory



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

BOE-C6-0212267